Kensington®

Release Notes

Kensington Konnect™ for Trackballs/Mice

for Windows

10/19/2026	
2.3.23	Updated log module to comply with the EU Data Act.
	Fixed issue affecting drag functionality during use.
09/01/2026	
2.3.19	Fixed issue with the TB675 wired connection.
07/31/2026	
2.3.17	TB900 supported.
	Fixed Macro function on the Windows login screen.
	Fixed in-app update issue.
	Added dongle connection notification.
06/15/2026	
2.3.1	TB675 trackball launch support.
	Improved loading issue.
05/11/2026	
2.2.3	Beta Internal testing.
05/06/2026	
2.2.2	Beta Internal testing.
03/20/2026	
2.1.18	Fixed Scroll direction for legacy scroll wheel behavior.
03/05/2026	
2.1.15	Beta Internal testing.
02/6/2026	
2.1.12	Fixed bug preventing successful removal of Kensington Works v3.1.8.
	Fixed bug causing button click settings to revert to default.
	Fixed bug causing in-app updates to fail.
	Fixed bug preventing Side Roller Configuration.
	Fixed bug preventing installation of Kensington Konnect v2.1.5.
01/23/2026	
2.1.10	Improved overall system stability.
	Updated trackball driver performance and compatibility.
	Updated virtual driver to enhance reliability.
	Improved language and character encoding support (UTF-8).
	Upgraded internal database for improved reliability of KensingtonWorks transition.
	Optimized background polling to reduce system load.

Kensington®

Release Notes

Kensington Konnect™ for Trackballs/Mice

for Windows

	Reduced CPU usage for smoother operation.
	Updated firmware SDK to support the latest device improvements.
12/5/2025	
2.1.1	Update all region translations.
11/17/2025	
2.1.0	Compatibility: Windows 10 or above.
	Fix bug with keyboard detection.
	Fix bug with macro assignment of button 6.
	Restore default value of F13 to F19.
	Supports TB800.
	Support to Horizontal/vertical scroll.
	Support to Navigation between tabs/all apps/desktops.
	Support to Set up speed of pointer w/o system setting effected.
10/15/2025	
2.0.0	Fix bug on keyboard detection.
	Fix bug on macro assignment of button 6.
	Fix bug on restore default value of F13 to F19.
	Fix bug on release modifier key.
	Supports SD7100T5: detection and configuration.
07/21/2025	
1.0.2	Fix bug on macOS installation issue.
	Fix bug on hotkey disappearing.
	Fixed loading/freezing issue at App start.
	Feature updates on feasibility of hiding/showing K logo.
	Support to adjust the step number of speed level bar.
	Support to red dot notification for update version.
02/20/2025	
1.0.1	Rename ProFit(R) to Pro Fit(TM).
	Fix bug on Google Drive sync.

acco BRANDS

All specifications are subject to change without notice. Products may not be available in all markets. Kensington® and Kensington, The Professionals' Choice™ are trademarks of ACCO Brands. All other registered and unregistered trademarks are the property of their respective owners. © 2026 Kensington Computer Products Group, a division of ACCO Brands. K26_4510

FOR MORE INFORMATION CONTACT: 1-855-692-0054 | sales@kensington.com

Kensington
The Professionals' Choice™