

KensingtonWorks™

for macOS

12/13/2019

(Official release version)

Version 2.1.8

Add ProFit Ergo Wired Mouse.
Add localization strings – “Scroll Right” and “Scroll Left”
Fix the localization bug of detecting from system locale.
Fix key chording bound “Scroll Left/Right”
Fix K64327, K72352, K72337 scroll up/ scroll down malfunction
Increase font size.

1/8/2020

Version 2.1.10

Fix [Mac] Pointer speed/Acceleration in BT mode can't be adjusted
Fix [Mac] Remove eject item
Add the support of Ergo Vertical Wireless Mouse
Update the image of Ergo Wired Mouse
Rename the KensingtonWorksAgent to KensingtonWorksHelper for issue that KensingtonWorks might be blocked by Accessibility after upgrade.
Change wording: Capture Selection to Clipboard
--> Capture to Clipboard Capture Selection to File
--> Capture to File
Delete GUI caches during installation.

2/21/2020

Version 2.1.13

Keep user Settings file during installation.
Fix bug: fail to add the application which name includes space.
Modify 'get latest package info' to ACCO server.
Solve the notarization process failed issue.
Fix Can't log in Google Drive when user selects “Bind to Cloud”

2/25/2020

Version 2.1.14

Feature change: define “second drag action” as “drag release”.
Change backup restore success message icon
Fix the bug of accessing the “user folder” with the name in uni-code.

3/20/2020

Version 2.1.15

Add feature: Track Scroll.
Remove TAU (test automation) commands “emulateButtonClick” & “emulateButtonPress” from release build for security concern.

4/20/2020

Version 2.1.16

Update “Copyright © 2020 ACCO Brands LLC.”
Add shortcut supported keys: backspace, arrowdown, arrowup.
Fix Single axis and slow pointer can't work normal when set different modifier key

5/14/2020

Version 2.1.17

Add “macOS Security & Privacy setting” guider to indicate user do following steps:

- a. Allow KensingtonWorks in Security & Privacy.
- b. Check KensingtonWorks in Input Monitoring.
- c. Check KensingtonWorks in Accessibility.

Implement localization of the guider.

Fix incorrect wording on traditional Chinese language environment and Japanese language environment by updating translation json files.

6/5/2020

Version 2.1.18

Add navigation feature - Auto Scroll.

- i. Click button to enable “Auto Scroll”;
- ii. Click any button to disable “Auto Scroll”;
- iii. Two scroll directions: horizontal and vertical.
- iv. Moving trackball to start “Auto Scroll” for 15 seconds (count down from the end of the moving of the trackball);
- v. During auto scrolling, “slightly/shortly” moving the trackball to change the direction will hold auto scroll;
- vi. During auto scrolling, normal moving the trackball to change the direction will change the direction of Auto scroll;
- vii. Limitation: for application specific setting for “Auto Scroll”, “Track Scroll” can’t be disabled by switch to another application until some button of the trackball is clicked.

Change UI flow:

- i. When launch KensingtonWorks, go to the trackball configure page directly if only single trackball is connected.
- ii. Go to the trackball configure page when a new trackball is plugged in.

9/15/2020

Version 2.1.19

1. 233 Add Orbit Fusion Trackball support

Fix “Media control shortcut” bug of ver.2.1.18

10/31/2020

Version 2.2.2

1. Improve the button event handling algorithm.
2. Fix issue Navigation “HOME” “PAGE UP” malfunctioned
3. Fix issue Left key and right key can’t be released after pressing simultaneously
4. Fix issue It takes two clicks to get the Left Drag to stick
5. Fix issue A combination of simultaneously pressed left and right trackball keys. Normally this simulates a middle mouse click, but it’s often interpreted as a drag and drop operation.
6. Fix issue Redefine the behavior of Double / Triple click to be the same as the one of TrackballWorks.
7. Dual driver support (add new DriverKit driver):
 - a. IOKit driver for macOS 10.15.3 and below
 - b. DriverKit driver for macOS 10.15.4 and above
8. Installer will install the required driver according to the OS version.
9. After installation, when the OS is upgraded from 10.15.3(and below) to 11.0 (or above), DriverKit driver will replace IOKit driver automatically



All specifications are subject to change without notice. Products may not be available in all markets. Kensington and the ACCO name and design are registered trademarks of ACCO Brands. Kensington The Professionals' Choice is a trademark of ACCO Brands. All other registered and unregistered trademarks are the property of their respective owners. © 2020 Kensington Computer Products Group, a division of ACCO Brands. All rights reserved. k20-3416-us

Kensington

The Professionals' Choice™