



VeriMark Windows 10 Manual Driver Install

Install the driver through Windows 10 Manual driver install


1. On the VeriMark support page, select **VeriMark** to go to the setup guides and driver download.




2. **Download** the driver from the VeriMark support page by clicking on the **“Manual driver install button”**.




3. The **compressed folder** will be downloaded to your specified location.




4. **Extract** the files of the compressed folder to a selected destination.




5. A **folder** with the extracted files will be created.




6. Go to **Device Manager** and right click on the unknown device and select **Update driver**.




7. Click on **“Browse my computer for drivers”**.




8. Select **Browse** to select a folder on your machine.




9. **Choose** the extracted folder location on **Step 4**.



10. Click **Next** to install the driver.



11. **Driver install** will take a couple of minutes.



12. Once **successfully installed** click close.



13. Kensington fingerprint key will show on device manager.

